Collection of Fugitive Emissions Components at a Compressor Station

§60.5420a(b)(7)

ne	Legal Entity	Survey Information												
		Date (b)(7)(i)	Beginning and End Time (b)(7)(ii)	Name, Training and Experience of OGI Operator (b)(7)(iii)	Ambient Temperature, Sky Conditions and Maximum Wind Speed (b)(7)(iv)	Monitoring Instrument (b)(7)(v)	Deviations (or Statement of No Deviations) (b)(7)(vi)	Number and Type of Components for Which Emissions Were Detected (b)(7)(vii)	Number and Type of Components Not Repaired as Required (b)(7)(viii)	Number and Type of DTM & UTM Components Monitored (b)(7)(ix)	Date of Successful Leak Repairs (b)(7)(x)	Number and Type of Components Placed on DOR and Explanation (b)(7)(xi)	Type of Instrument Used to Resurvey a Repaired Component (not during the initial finding) (b)(7)(xii)	Deviations (If deviations occurred bla
mpressor Station	EQM Gathering Opco	8/28/2018	1:20 PM-2:40 PM	Dan Neidermeyer-Trained	94 deg F Sunny 1.6 mph	FLIR GFx320 OGI Camera	No	None (no leaks detected)	None	None	NA	NA	NA	
ipressor Station	EQM Gathering Opco	10/31/2018	9:00 AM-11:00 AM	Dan Neidermeyer-Trained	62 deg F Cloudy 3.1 mph	FLIR GFx320 OGI Camera	No	None (no leaks detected)	None	None	NA	NA	NA	
pressor Station	EQM Gathering Opco	1/28/2019	2:15 PM-3:30 PM	Dan Neidermeyer-Trained	44deg F Sunny/Clear 2.3 mph	FLIR GFx320 OGI Camera	No	None (no leaks detected)	None	None	NA	NA	NA	
ressor Station	EQM Gathering Opco	4/29/2019	2:00 PM-4:30 PM	Dan Neidermeyer-Trained	73.7 deg F Sunny 1.1 mph	FLIR GFx320 OGI Camera	No	None (no leaks detected)	None	None	NA	NA	NA	
essor Station	EQM Gathering Opco	7/16/2019	9:00 AM-9:45 AM	Dan Neidermeyer-Trained	78 deg F Sunny 1 mph	FLIR GFx320 OGI Camera	No	None (no leaks detected)	None	None	NA	NA	NA	
ressor Station	EQM Gathering Opco	8/14/2018	9:45 Am-11:14 AM	L. Mays- Certified	67 deg F Overcast 2.4 mph	FLIR GFx320 OGI Camera	No	One (1) Bleed valve/blowdown One (1) Fitting- Dehy 1 One (1) Discharge Filter vessel One (1) Produced fluids tank vent	None	None	8/28/2018	None	FLIR GFx320 OGI Camera	
essor Station	EQM Gathering Opco	12/7/2018	10:30 AM-12:30PM	Jason Cypher - Trained	33 deg F Sunny/Clear 3 mph	FLIR GFx320 OGI Camera	No	One (1) Plug- contact tower 2	None	None	12/11/2018	None	FLIR GFx320 OGI Camera	