through (xii) of this section in all annual reports:

Each Component Type Fugitive Emissions Detected * (§60.5420a(b)(7)(vii))	Type of Component Not Repaired as Required in §60.5397a(h) * (§60.5420a(b)(7)(viii))	Number of Each Component Type Not Repaired as Required in § 60.5397a(h) * (§60.5420a(b)(7)(viii))	Type of Difficult-to-Monitor Components Monitored * (§60.5420a(b)(7)(ix))	Number of Each Difficult-to-Monitor Component Type Monitored * (§60.5420a(b)(7)(ix))	Type of Unsafe-to-Monitor Component Monitored * (§60.5420a(b)(7)(ix))	Number of Each Unsafe-to-Monitor Component Type Monitored * (§60.5420a(b)(7)(ix))	Date of Successful Repair of Fugitive Emissions Component * (§60.5420a(b)(7)(x))	Type of Component Placed on Delay of Repair * (§60.5420a(b)(7)(xi))	Number o Component Ty on Delay of (§60.5420a(l
e.g.: Valve		e.g.: 1	e.g.: Valve	e.g.: 1	e.g.:Valve	e.g.: 1	e.g.: 11/10/16	e.g.: Valve	e.g.: 1
4	NA		0 None		0 None		0	11/10/2018 NA	
1	NA		0 None		0 None		0	11/7/2018 NA	
1	NA		0 None		0 None		0	11/7/2018 NA	
5	NA		0 None		0 None		0	11/6/2018 NA	
4	NA		0 None		0 None		0	11/6/2018 NA	
8	NA		0 None		0 None		0	11/6/2018 NA	
6	NA		0 None		0 None		0	11/5/2018 NA	
11	NA		0 None		0 None		0	11/9/2018 NA	
4	NA		0 None		0 None		0	11/12/2019 NA	
2	NA		0 None		0 None		0	11/12/2019 NA	
2	NA		0 None		0 None		0	11/15/2019 NA	
3	NA		0 None		0 None		0	11/10/2018 NA	
0	NA		0 None		0 None		0 NA	NA	
5	NA		0 None		0 None		0	5/14/2019 NA	
4	NA		0 None		0 None		0	5/14/2019 NA	
3	NA		0 None		0 None		0	5/24/2019 NA	
2	NA		0 None		0 None		0	5/14/2019 NA	
1	NA		0 None		0 None		0	5/14/2019 NA	
5	NA		0 None		0 None		0	5/24/2019 NA	
1	NA		0 None		0 None		0	5/24/2019 NA	
1	NA		0 None		0 None		0	5/24/2019 NA	
0	NA		0 None		0 None		0 NA	NA	
1	NA		0 None		0 None		0	5/24/2019 NA	