									OGI	Compressor Station Affected F	
Difficult-to-Components ıitored * 20a(b)(7)(ix))	Number of Each Difficult-to-Monitor Component Type Monitored * (§60.5420a(b)(7)(ix))	Type of Unsafe-to-Monitor Component Monitored * (§60.5420a(b)(7)(ix))	Number of Each Unsafe-to-Monitor Component Type Monitored * (§60.5420a(b)(7)(ix))	Date of Successful Repair of Fugitive Emissions Component * (§60.5420a(b)(7)(x))	Type of Component Placed on Delay of Repair * (§60.5420a(b)(7)(xi))	Number of Each Component Type Placed on Delay of Repair * (§60.5420a(b)(7)(xi))	Explanation for Delay of Repair * (§60.5420a(b)(7)(xi))	Type of Instrument Used to Resurvey Repaired Components Not Repaired During Original Survey * (§60.5420a(b)(7)(xii))	Training and Experience of Surveyor * (§60.5420a(b)(7)(iii))	Was a monitoring survey waived under § 60.5397a(g)(5)? * (§60.5420a(b)(7))	If a monitoring calendar mo quarterly mon the monitorin (§60
e.g.: 1	e.g.:Valve	e.g.: 1	e.g.: 11/10/16	e.g.: Valve	e.g.: 1	e.g.: Unsafe to repair until next shutdown	e.g.: Company ABC optical gas imaging camera	e.g.: Trained thermographer; completed 40-hour course at XYZ Training Center. Has 10 years of experience with OGI surveys.	e.g.: Yes	e.g.: January; Fe	
0	0	n/a	0	5/17/2019	n/a	0	n/a	n/a	Trained thermographer; Has 4 years of experience with OGI su	No	n/a
0	0	n/a	0	10/22/2018	n/a	0	n/a	n/a	Trained thermographer; Has 4 years of experience with OGI su	No	n/a